

DELHI JAL BOARD: GOVT. OF NCT OF DELHI
OFFICE OF THE EXECUTIVE ENGINEER (RWH/GWC)
ROOM NO. 209, VARUNALAYA PHASE-I
KAROL BAGH, NEW DELHI - 110005
23558264

No./DJB/EE(RWH/GWC)/2018/8419

DATED: 18/12/18

To,

The Principal
COSMOS Public School
Molarband Extn., Tajpur
Badarpur, Delhi-44


Subject:-Regarding adequacy of rain water harvesting system at COSMOS Public School, Molarband Extn., Tajpur, Badarpur, Delhi-44.

Sir/Madam,

The above said unit has been inspected by Joint Inspection Team on 18.12.2018, constituted by Hon'ble NGT in O.A. No. 217/2016. It was found that one No. RWH pit is existing at site.

The existing RWH structure is functional and adequate to harvest the roof top run-off for catchment area of (roof top-5225 sqft.) of above said unit. The RWH structure was found functional at the time of inspection.

You are advised to keep the existing RWH system neat & clean & maintain the same periodically.


EE (RWH/GWC)

EE (G.W. TULL)
DELHI JAL BOARD
VARUNALAYA PHASE-I,
JHANDEWALLAN, N.D.-05